## DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-009491 Address: 333 Burma Road **Date Inspected:** 04-Sep-2009

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1600 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** N/A **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG Deck Panels** 

# **Summary of Items Observed:**

On this day Caltrans OSM Quality Assurance (QA) Inspector Stefan Holmes was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhen Hua Port Machinery Company (ZPMC) at Chang Xing Island in Shanghai, China.

Continued training and turnover of deck panel documentation and responsibilities to new QA Inspector. QA Inspector worked on Document Control for U-rib deck panels. Deck panel PAUT reports input and updated for lift 10 and 11 deck panels. Deck panel PAUT reports organized and copied for transmittal and summary update. Deck panel log for lifts 10 and 11 deck panel assemblies updated and the Complete deck panel log updated.

QA Inspector continued organizing Deck Panel reports for archive. SMR deck panel summary spreadsheet reviewed and corrected. SMR Deck Panel Tack Weld Assessment Summary updated.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

#### **Summary of Conversations:**

No relevant conversations.

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact, who represents the Office of Structural Materials for your project.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

**Inspected By:** Holmes,Stefan Quality Assurance Inspector **Reviewed By:** Hall,Steven QA Reviewer